

Maritime Safety Queensland
Queensland Notices to Mariners

624 (Temporary) of 2009

Townsville pilotage area

Locality: Ross Creek

Activity: Temporary buoys

Refer to notice: 578 (T) of 2009

Mariners are advised that the pile beacons at the entrance to Ross Creek, adjacent to berth 10 have been removed and have been replaced with temporary lateral buoys in the following positions:

Port hand buoy	Fl.R3s	latitude 19° 15.0276' S, longitude 146° 49.7962' E
Starboard hand buoy	Fl.G3s	latitude 19° 15.0109' S, longitude 146° 49.7666' E

The temporary buoys will remain until new pile beacons are re-established.

Cancel notice: 578 (T) of 2009

AUS charts affected: 256, 827

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 18 September 2009