

Maritime Safety Queensland  
Queensland Notices to Mariners

**144 (Temporary) of 2011**

---



**Townsville pilotage area**

**Locality:** Cleveland Bay

**Activity:** temporary buoy established

**Refer to notice:** 120 (T) of 2011

Mariners are advised that a temporary isolated danger mark buoy Iso 2s and Fl (2) 6s has been established in approximate position latitude 19° 12.267' S, longitude 146° 51.752 ' E to identify the navigation hazard of the partially submerged Sea Channel rear lead.

Mariners are advised to keep clear within a 50 metre radius of the established temporary buoy. Mariners are advised to navigate with caution whilst operating in this area.

**AUS charts affected:** 256 and 827

**Maritime Safety Queensland charts affected:** none

---

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

**For further information about this notice, please contact:**

The Townsville Regional Harbour Master's office on 07 4726 3400

**Authorised by:** Director (Maritime Services)

**Issued:** Brisbane 11 February 2011