

Maritime Safety Queensland
Queensland Notices to Mariners

143 (Permanent) of 2012

Townsville pilotage area

Locality: Ross River entrance

Activity: starboard lateral No. 1 buoy re-established

Refer to notice: 131 (T) of 2012

Mariners are advised that the Ross River starboard lateral buoy Fl G 2.5s has been re-established in approximate position latitude 19° 15.30' S, longitude 146° 50.85' E.

Cancel notice: 131 (T) of 2012

AUS charts affected: 256, 257 & 827

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 13 February 2012