

Maritime Safety Queensland
Queensland Notices to Mariners

1044 (Permanent) of 2011

Townsville pilotage area

Locality: Nelly Bay Harbour

Activity: Entrance channel marks - light characteristics altered.

Mariners are advised that the light characteristics of the following beacons marking the entrance channel to Nelly Bay harbour have been altered from Fl 4.3s to Fl 1.5s.

Beacon

No. 1	latitude 19 09.7464'S	longitude 146 51.3675'E	Fl G 1.5s
No. 2	latitude 19 09.7466'S	longitude 146 51.3429'E	Fl R 1.5s
No. 3	latitude 19 09.6890'S	longitude 146 51.3660'E	Fl G 1.5s
No. 4	latitude 19 09.6900'S	longitude 146 51.3425'E	Fl R 1.5s
No. 5	latitude 19 09.6291'S	longitude 146 51.3683'E	Fl G 1.5s
No. 6	latitude 19 09.6284'S	longitude 146 51.3404'E	Fl R 1.5s

The lights are synchronised to flash simultaneously.

AUS charts affected

256

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 26 October 2011