

Maritime Safety Queensland
Queensland Notices to Mariners
496 (Temporary) of 2011

Townsville pilotage area

Locality: Palm Island

Activity: lead lights reported unlit

Mariners are advised that the Palm Island entrance front and rear lead lights have been reported unlit.

Mariners are advised to navigate with caution in this area.

AUS charts affected: 827, 828

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 1 June 2011