

Maritime Safety Queensland
Queensland Notices to Mariners

843 (Temporary) of 2010

Townsville pilotage area

Locality: Ross River

Activity: temporary beacon established

Mariners are advised that a lit special mark lateral beacon Fl Y 5s has been established in position latitude 19° 16.069' S, longitude 146° 50.256' E to mark a water quality monitor.

Mariners are advised to keep a clear distance of 50 metres from the position. The water quality monitor is estimated to be in place until 30 June 2011.

AUS charts affected: 256, 257

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 30 September 2010