

Maritime Safety Queensland  
Queensland Notices to Mariners  
**1236 (Permanent) of 2011**

---

**Townsville pilotage area**

**Locality:** Townsville Outer Harbour

**Activity:** Relocation of Special Mark Bouys

**Refer to notice:** 1090 (T) of 2011

Mariners are advised that the two special mark buoys with light characteristics Fl Y 4s marking the eastern limit of the berth 11 approach basin have now been moved back into position.

- Inshore - latitude 19° 14.610' S, longitude 146° 50.347' E
- Offshore - latitude 19° 14.579' S, longitude 146° 50.373' E

**Cancel notice:** 1090 (T) of 2011

**AUS charts affected:** 256, 257 & 827

**Maritime Safety Queensland charts affected:** none

---

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

**For further information about this notice, please contact:**

The Townsville Regional Harbour Master's office on 07 4726 3400

**Authorised by:** Director (Maritime Services)

**Issued:** Brisbane 12 December 2011