

015 (Temporary) of 2011

Townsville pilotage area

Locality: Townsville approach channels, harbours and berths

Activity: amended port navigation depths

Refer to notice: 1089(t) of 2011

Mariners are advised that the actual navigation depths below port datum (Lowest Astronomical Tide) are amended as of 05 January 2012 as follows:

	Actual Depths (metres)	Remarks
Outer Harbour (Arrival Channel)	7.0	
Outer Harbour (Departure Channel)	10.9*	
Sea Channel	11.7	
Platypus Channel	11.7*	
Harbour	11.5	
No. 1 Berth Pocket	11.2*	
No. 2 Berth Pocket	11.3*	
No. 3 Berth Pocket	11.8	
No. 4 Berth	10.5*	Berth Pocket only
	9.5*	Arrival to or Departure from 0 mark
	10.1*	Arrival to or Departure from 10 mark*
	10.5*	Arrival to or Departure from 20 mark*
No. 7 Berth Pocket	10.5*	
Between No. 7 and No. 8	9.8	Seaward of zero mark at No.7
No. 8 Berth Pocket	9.0*	
No. 9 Berth Pocket	11.4*	
Between No. 9 and No. 10	10.2*	Seaward of zero mark at No.10
No. 10 Berth Pocket	9.2*	From 10m to seaward dolphin
	9.2*	From RORO mark to 10m mark
No. 11 Berth Pocket	11.3*	
Ross River Channel	No declared depth	
Ross River	No declared depth	
Ross Creek	No declared depth	

* Revised entry

Cancel notice: 1089 (t) of 2011

AUS charts affected: 256, 257

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane Thursday January 5 2012