

Maritime Safety Queensland  
Queensland Notices to Mariners

**625 (Permanent) of 2011**

---

**Townsville pilotage area**

**Locality:** Ross River, Townsville

**Activity:** new port lateral beacon established

Mariners are advised that a new port lateral beacon with light characteristics Fl R 4s has been established in position latitude 19° 15.756' S, longitude 146° 50.522' E.

**AUS charts affected:** 256, 257 & 827

**Maritime Safety Queensland charts affected:** none

---

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

**For further information about this notice, please contact:**

The Townsville Regional Harbour Master's office on 07 4726 3400

**Authorised by:** Director (Maritime Services)

**Issued:** Brisbane 12 July 2011