

Maritime Safety Queensland
Queensland Notices to Mariners

017 (Permanent) of 2012

Townsville pilotage area

Locality: Ross Creek

Activity: special mark buoy altered in position

Refer to notice: 014 (p) of 2012

Mariners are advised that the special mark buoy Fl Y 1.5s displaying the words "No Anchoring" has been relocated to approximate position latitude 19° 15.496' S, longitude 146° 49.521' E.

Anchoring of ships is prohibited in this area.

Cancel notice: 014 (P) of 2012

AUS charts affected: 256, 257

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 9 January 2012