

Maritime Safety Queensland
Queensland Notices to Mariners

669 (Temporary) of 2011

Townsville pilotage area

Locality: Nelly Bay Harbour

Activity: turbidity monitoring buoy deployed

Mariners are advised that a turbidity monitoring buoy, special mark Fl Y 4s has been established in position latitude 19° 09.680' S, longitude 146° 51.380' E. The buoy will be in this position until Friday, 30 September 2011.

Mariners are requested to keep clear of this buoy and obey the no wash sign located on it.

AUS charts affected: 256, 827

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 20 July 2011