

Maritime Safety Queensland
Queensland Notices to Mariners
412 (Permanent) of 2011

Townsville pilotage area

Locality: Bay Rock

Activity: Reported light out

Refer to notice: 297 (t) of 2011

Mariners are advised that the isolated danger light Fl.(2)8s in position latitude 19°07.025'S, longitude 146°45.232'E has been restored to normal operation.

Cancel notice: 297 (t) of 2011

AUS charts affected: 256 & 827

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 9 May 2011