

QUEENSLAND
NOTICE TO MARINERS
284 (Temporary) of 2009

Maritime Safety
Queensland

Queensland Transport

OUTSIDE PILOTAGE AREAS

LOCALITY: CAPE MORETON

ACTIVITY: UNDERWATER OBSTRUCTION

Refer to Notice: 202 (T) of 2009

Mariners are advised that underwater obstructions have been reported within a 0.5 nautical mile radius of the following approximate positions:

- A. latitude 27° 00.7' S, longitude 153° 35.3' E
- B. latitude 27° 01.7' S, longitude 153° 36.0' E
- C. latitude 27° 02.2' S, longitude 153° 35.7' E

Mariners engaged in trawling are strongly recommended to not use this area.

Mariners are advised to navigate with caution and avoid the area if possible.

AUS Charts Affected: 235

Maritime Safety Queensland Charts Affected: Moreton Bay – Manly to Mooloolaba (MB1)

Maritime Safety Queensland Beacon to Beacon Directory 8th Edition map 5

NOTE: Latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this Notice, please contact:

The Brisbane Regional Harbour Master's office on 07 3860 3500.

Authorised by: DIRECTOR (MARITIME SERVICES)

Issued: Brisbane 8 May 2009