

Maritime Safety Queensland
Queensland Notices to Mariners

554 (Temporary) of 2011



Abbot Point pilotage area

Locality: Abbot Point bulk coal facility - new berth

Activity: hazard to navigation

Mariners are advised that 18 metres of 12 millimetre diameter hose with brass fittings has been lost into the water adjacent to the new berth at the Abbot Point bulk coal ship loading facility.

Mariners are advised to keep well clear of Berth 2 (the new berth) and navigate with caution while operating in this area.

AUS charts affected: 255, 825

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 17 June 2011