

Maritime Safety Queensland
Queensland Notices to Mariners
896 (Permanent) of 2011

Townsville pilotage area

Locality: Ross River, Townsville Marine Precinct

Activity: new entrance beacons established

Mariners are advised that land based beacons have been established to mark the entrance to the Townsville Marine Precinct in the following positions:

- starboard lateral Green Fl G 4s - latitude 19° 15.654' S, longitude 146° 50.521'E
- north cardinal mark Q White - latitude 19° 15.704' S, longitude 146° 50.497' E

AUS charts affected: 256, 257 & 827

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 22 September 2011