

521 (Permanent) of 2011

Townsville pilotage area

Locality: Sea Channel Lead Lights

Activity: lead light characteristics

Refer to notice: 472 (P) of 2011

Mariners are advised that the Sea Channel front and rear lead lights and isolated danger beacon characteristics are as follows:

Sea Channel Lead & P4 Beacon - Q & Fl R 4s (night-lights) and F Day (day-light)

Sea Channel Rear Lead & Isolated Danger Beacon - Iso 2s & Fl (2) 6s (night-lights) and F Day (day-light)

AUS charts affected: 256, 257 & 827

Maritime Safety Queensland charts affected: none

Note: latitude and longitude positions on WGS84 horizontal datum (compatible with GDA94 datum).

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office on 07 4726 3400

Authorised by: Director (Maritime Services)

Issued: Brisbane 9 June 2011